Jack Branch Subdivision

Part of

Section 6, T. 2 S., R. 46 E., B.M.

BONNEVILLE COUNTY, IDAHO

LINE	DIRECTION	DISTANCE
L1	N 60°55'19" E	46.78'
L2	N 66°00'21" E	56.48'
L3	N 81°55'26" E	58.94'
L4	S 82°19'28" E	89.16'
L5	S 85°52'16" E	59.51'
L6	S 77°22'12" E	63.25'
L7	N 84°26'31" E	74.80'
L8	N 63°54'00" E	68.61'
L9	N 39°08'46" E	72.27'
L10	N 77°03'09" E	42.47'
L11	S 67°50'39" E	81.24'
L12	S 50°22'33" E	54.23'
L13	N 62°23'35" E	151.65'
L14	N 54°58'52" E	61.88'
L15	S 67°28'28" E	117.10'
L16	N 37°18'11" E	30.79'
L17	N 52°09'52" W	81.83'
L18	N 38°08'53" W	77.86'
L19	S 80°38'44" W	125.13'
L20	N 41°30'54" W	146.11'
L21	N 78°12'26" W	217.65'
L22	N 01°19'56" E	86.15'
L23	N 55°22'34" W	103.42'
L24	N 11°44'10" W	163.03'



LEGEND

- Section control corners
- Placed 1/2" iron rod with cap marked P.L.S. 4563
- Placed 5/8" x 30" iron rod with cap marked P.L.S. 4563
- Highway Right of way monuments
- Found 1/2" iron rod w/cap marked LS 827 replaced w/ 5/8" iron rod w/cap marked LS 4563

First American Title Company

Idaho Falls, Idaho 83404

This sketch is made solely for the purpose of assisting in locating the premises The company assumes no liability for alleged loss or damage which may result from reliance on this map.

FIRST AMERICAN