


THAYER BRIDGE





DIVISION NO. 1

TOWNHOUSES

PART OF THE
S.E. 1/4, OF SEC. 25 T.2 N. R.37 E., B.M.




LEGEND

-  Section control corners
-  Placed 1/2" iron rod with cap marked P.L.S. 4563
-  Unit No.
-  Garage Unit No.



First American Title Company
 Idaho Falls, Idaho 83404
 This sketch is made solely for the purpose of assisting in locating the premises. The company assumes no liability for alleged loss or damage which may result from reliance on this map.



UNIVERSITY MICROFILMS